DP 500/510 - Mobile dew point meters with data logger

Applications:

- Compressed air: Examination of refrigeration, membrane, adsorption dryers
- Technical gases: Residual moisture measurement in gases such as N2, O2 etc.
- · Plastic industry: Examination of granulate dryers

Transfer of data per USB stick to the PC 2nd freely assignable sensor

Special features:

- Precise dew point measurement down to -80°Ctd
- · Quick response time
- 3.5" graphic display / easy operation via touch screen
- Integrated data logger for storage of the measured values
- USB interface for reading out via USB stick
- Calculates all necessary moisture parameters like g/m³, mg/m³, ppm V/V, g/kg, °Ctdatm
- 2nd freely assignable sensor input for third-party sensors (only DP 510)
- · International: Up to 8 languages selectable



Quick installation by means of measuring chamber and quick connector



Ideal for service technicians - everything in one case



Dry container - for sensor protection and quick adaptation time





input for third-party sensors

(only DP 510)

Flow meter

VA 520







Current/effective power meter


Screw-in Third-party sensor temperature probe 0-1/10 V
Pt 1000 (0) 4...20 mA

Pulse Modbus/RS 485


The whole range of suitable sensors can be found on pages 30 to 33

VA 500

Everything a glance



Gradients are displayed graphically, so the operator sees at a glance the behavior of the dryer since the start of the measurement.



All physical parameters of the humidity measurement are calculated automatically. The DP 510 also displays the measured values of the external sensor.

	*** L	ogger settings	***	
		me interval (se		
1 2	5 1	0 15 30	60 120	0 15
force	e new rec	ord file		
Comment:		Dryer Trock	ener 13	
Logger s	topped	timed St	tart 🔽	timed Stop
START	STOP	12:26:00 - 0	6.0 13:28	B:00 - 06.0
		ing logger capacit		ys
Back Logging: 0 channels selected time interval (min 1 sec				

Up to 100 million readings can be stored. Each measurement may be accompanied by a comment, e. g. location name. The time interval can be determined freely.

DESCRIPTION	ORDER-NO.
Set DP 500 in a case - consisting of:	0600 0500
- Portable dew point meter DP 500 for compressed air and gases	0560 0500
- Mobile measuring chamber up to 16 bar	0699 4490
- Diffusion-tight PTFE hose with quick connector, length 1 m	0554 0003
- Power supply for DP 500/510	0554 0009
- Control and calibration set 11.3 % RH	0554 0002
- Quick-lock coupling	0530 1101
- Dry container for CS dew point sensors	0699 2500
- Transportation case (small) for DP 500	0554 6500
Set DP 510 in a case - consisting of:	0600 0510
- Mobile dew point meter DP 510 with one additorial input	0560 0510

. •	
- Dry container for CS dew point sensors	0699 2500
- Transportation case (small) for DP 500	0554 6500
Set DP 510 in a case - consisting of:	0600 0510
- Mobile dew point meter DP 510 with one additorial input external sensors	0560 0510
- Mobile measuring chamber up to 16 bar	0699 4490
- Diffusion-tight PTFE hose with quick connector, length 1 m	0554 0003
- Power supply for DP 500/510	0554 0009
- Control and calibration set 11.3 % RH	0554 0002
- Quick-lock coupling	0530 1101
- Dry container for CS dew point sensors	0699 2500
- Transportation case (large) for DP 510 as well as other sensors	0554 6510
Furter options, not included in the set:	
Option: "Mathematics calculation function" for 4 freely selectable channels, (virtual channels): addition, subtraction, division, multiplication	Z500 5107
Option: "Totalizer function for analogue signals"	Z500 5106
CS Basic – data evaluation graphically and in tabular form - reading of the measured data via USB or Ethernet, license for 2 workstations	0554 8040
Precision calibration at -40°Ctd or 3°Ctd with ISO certificate	0699 3396
Additional calibration point freely selectable in the range between -80+20°Ctd	0700 7710
High pressure measuring chamber up to 350 bar	0699 3590
Measuring chamber for atmospheric dew point	0699 3690

Measuring chamber for granulate driers with minimum overpressure

Portable dew point meter DP 510 for compressed air and gases

Portable dew point meter DP 500 for compressed air and gases

(high pressure version up to 350 bar)

(high pressure version up to 350 bar)



Photo key saves current screen as an image file. No additional software necessary.

TECHNICAL DATA DP 500/510				
Display:	3.5" Touch screen			
Measuring range:	-80+50°Ctd -20+70°C 0100 %rF			
Accuracy:	± 0,5°Ctd bei -10+50°Ctd Typ. ± 2°Ctd (remain. range)			
Moisture parameters:	g/m³, mg/m³, ppm V/V, g/kg, °Ctdatm, %rF			
Pressure range:	-150 bar standard -1350 bar special version			
Interface:	USB interface			
Data logger:	8 GB SD memory card (100 millions values)			
Power supply for sensors:	Output voltage: 24 VDC ± 10% Output current: 120 mA continuous operation			
Power supply:	Internal rechargeable Li-lon batteries, approx 12 h continuous operation, 4 h charging time			
Screw-in thread:	G 1/2" stainless steel			
Ambient temperature:	0+50°C			
EMV:	DIN EN 61326-1			

0699 3490

0560 0512

0560 0501